



## Photographic Documentation

**Name of Facility:** Partners Produce, Payette

**Inspector(s):** Albert Crawshaw and Tom Talley

**Inspection Date:** Thursday, April 09, 2020

**Purpose of Inspection:** Complaint investigation

### Table of Photographs:

Photograph 1 :Stormwater swale located on the northeast side of the facility, looking south.....	5
Photograph 2 :Close up view of stormwater swale located on the northeast side of the facility, looking south.....	5
Photograph 3 :Close up view of outfall pipe to stormwater swale located on the northeast side of the facility, looking south. ....	6
Photograph 4 :Irrigation ditch located on the northside of the facility, looking west. ....	6
Photograph 5 :View of the stormwater swale located on the northeast side of the facility, looking through vegetation facing south. ....	7
Photograph 6 :Closeup view of the stormwater swale located on the northeast side of the facility, looking through vegetation facing south. ....	7
Photograph 7 :Second closeup view of the stormwater swale located on the northeast side of the facility, looking through vegetation facing south.....	8
Photograph 8 :Stormwater swale located on the north side of the facility, looking through vegetation facign south.....	8
Photograph 9 :Closeup view of stormwater swale located on the north side of the facility, looking through vegetation facign south. ....	9
Photograph 10 :Stormwater swale, thorough vegetation, north side of the facility, looking at the central area facing south. ....	9
Photograph 11 :Closeup view of stormwater swale, thorough vegetation, north side of the facility, looking at the central area facing south.....	10
Photograph 12 :Rills on the northside of the facility, irrigation ditch is in the foreground, looking south. ....	10
Photograph 13 :Irrigation ditch on northside of the property, looking west. ....	11

Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020

Photograph 14 :Irrigation ditch on northside of the property, looking northwest, moist soil in bottom of irrigation ditch. ....	11
Photograph 15 :Closeup view of irrigation ditch on northside of the property, looking northwest, moist soil in bottom of irrigation ditch.....	12
Photograph 16 :Irrigation ditch area observed in video attached to compalint file, Complaint #160717 Video.mov.....	12
Photograph 17 :Closeup view of irrigation ditch area observed in video attached to compalint file, Complaint #160717 Video.mov. ....	13
Photograph 18 :Irrigation ditch on the west side of the property, north side and west side irrigation ditches meet in the foreground, looking southwest.....	13
Photograph 19 :Closeup up view of pooling water in west side irrigation ditch, looking southwest. ....	14
Photograph 20 :Stormwater swale located on the west side of the property, looking southwest. ....	14
Photograph 21 :Close up view of stormwater swale located on the west side of the property, looking southwest.....	15
Photograph 22 :Stormwater swale, Swale #1, located on the east side of the property near the onion hopper from the largest building on the property. View is looking southwest.....	15
Photograph 23 :Closeup view of Swale #1, looking southwest. ....	16
Photograph 24 :Water in Swale #1. ....	16
Photograph 25 :Stormwater outfall to Swale #1, looking southwest.....	17
Photograph 26 :Stormwater outfall and water, Swale #1, note onion husk and debris in water. ....	17
Photograph 27 :Stormwater swale, Swale #2, located on the northeast corner of the property, looking north northeast.....	18
Photograph 28 :Stormwater outfall to Swale #2, looking north.....	18
Photograph 29 :Swale #2, looking north.....	19
Photograph 30 :Rills on west bank of Swale #2 near south end of the swale. ....	19
Photograph 31 :Swale #2, mid-way, looking north, note rills along west bank....	20
Photograph 32 :Closeup view of west bank, mid-way, rills, Swale #2. ....	20
Photograph 33 :Swale #2, northend, looking northwest.....	21
Photograph 34 :Closeup view of northend rills, Swale #2. ....	21
Photograph 35 :Swale #2, northend, looking north.....	22
Photograph 36 :Closeup view of erosion area, Swale #2, northend.....	22
Photograph 37 :Swale #2, looking southwest.....	23
Photograph 38 :Swale #2, looking southwest, note rills on west bank. ....	23
Photograph 39 :Sromwater swale, Swale #3, located on the north side of the property, looking northwest. ....	24
Photograph 40 :Swale #3, northest end, looking northwest. ....	24
Photograph 41 :Closeup view of Swale #3, northest end. ....	25
Photograph 42 :Irrigation ditch and vegetation on the north side of the property near Swale #3. ....	25

Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020

Photograph 43 :Closeup view of Swale #3, northeast end, note onion and onion husks. ....	26
Photograph 44 :Closeup view of Swale #3, northeast end, note discoloration of soil, appears to be oil or petroluem based. ....	26
Photograph 45 :Refrigeration oil drums, stored on the north end of the property, near Swale #3. Facility representative indicated the drums contained used oil. .	27
Photograph 46 :Label on one of the drums. ....	27
Photograph 47 :Refrigeration oil drums, note oil pooling on the top and leaking around the sides.....	28
Photograph 48 :Storage pallets and refrigeration oil drums. ....	28
Photograph 49 :Leaking oil from refrigeration oil drums on to storage pallets. ..	29
Photograph 50 :Refrigeration oil drums, stored near Swale #3, looking east. ....	29
Photograph 51 :Refrigeration oil drums, stored near Swale #3, looking east, second view.....	30
Photograph 52 :Swale #3, west end of the swale, looking east.....	30
Photograph 53 :Swale #3, west end of the swale, looking east, second view.....	31
Photograph 54 :Rills on southwest bank of Swale #3.....	31
Photograph 55 :Swale #3, looking east.....	32
Photograph 56 :Rills on south bank of Swale #3.....	32
Photograph 57 :Irrigation ditch on north side of property looking west, note moist soil in ditch bottom does not extend to foreground. ....	33
Photograph 58 :Rills on facility property into north side irrigation ditch.....	33
Photograph 59 :Irrigation ditch and moist soil on north side of property, looking north.....	34
Photograph 60 :Closeup view of moist soil in irrigation ditch north side of property. ....	34
Photograph 61 :Large rill on facility property into north side irrigation ditch, looking east. ....	35
Photograph 62 :Large rill on facility property into north side irrigation ditch, looking north.....	35
Photograph 63 :Irrigation ditch on west side of proeprty looking north.....	36
Photograph 64 :Pooling water in irrigation ditch, west side of the porerty, looking north.....	36
Photograph 65 :Stormwater swale, Swale #4, lacated on the west side of the property, looking southwest. ....	37
Photograph 66 :Swale #4, northeast end, looking southwest, note tire tracks to edge of swale. ....	37
Photograph 67 :Swale #4, north end, looking northwest. ....	38
Photograph 68 :Closeup view of Swale #4 north end.....	38
Photograph 69 :Swale #4, looking north from the south end. ....	39
Photograph 70 :Closeup view of Swale #4, southend.....	39
Photograph 71 :Closeup view of Swale #4, note onions and debris.....	40

Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020

Photograph 72 :West side of property near waste water truck loading station, betwen station and Swale #4, looking northwest. ....	40
Photograph 73 :West side of property looking at pooling water and Swale #4, facing north. ....	41
Photograph 74 :Waste water truck loading station located on the west side of the property. ....	41
Photograph 75 :View from waste water truck loading station looking west southwest.....	42
Photograph 76 :Rills and waste water from truck loading operations. ....	42



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 1 :Stormwater swale located on the northeast side of the facility, looking south.



Photograph 2 :Close up view of stormwater swale located on the northeast side of the facility, looking south.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 3 :Close up view of outfall pipe to stormwater swale located on the northeast side of the facility, looking south.



Photograph 4 :Irrigation ditch located on the north side of the facility, looking west.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 5 :View of the stormwater swale located on the northeast side of the facility, looking through vegetation facing south. Filming location for video\_1 in complaint file #160717.



Photograph 6 :Close-up view of the stormwater swale located on the northeast side of the facility, looking through vegetation facing south.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 7 :Second close-up view of the stormwater swale located on the northeast side of the facility, looking through vegetation facing south.



Photograph 8 :Stormwater swale located on the north side of the facility, looking through vegetation facing south.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 9 :Close-up view of stormwater swale located on the north side of the facility, looking through vegetation facing south.



Photograph 10 :Stormwater swale, through vegetation, north side of the facility, looking at the central area facing south.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 11 :Close-up view of stormwater swale, through vegetation, north side of the facility, looking at the central area facing south.



Photograph 12 :Rills on the north side of the facility, irrigation ditch is in the foreground, looking south.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 13 :Irrigation ditch on north side of the property, looking west.



Photograph 14 :Irrigation ditch on north side of the property, looking west, moist soil in bottom of irrigation ditch.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 15 :Close-up view of irrigation ditch on north side of the property, looking west, moist soil in bottom of irrigation ditch.



Photograph 16 :Irrigation ditch area observed in video attached to complaint file, Complaint #160717 Video.mov.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 17 :Close-up view of irrigation ditch area observed in video attached to complaint file, Complaint #160717 Video.mov.



Photograph 18 :Irrigation ditch on the west side of the property, north side and west side irrigation ditches meet in the foreground, looking southwest.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 19 :Close-up up view of pooling water in west side irrigation ditch, looking southwest.



Photograph 20 :Stormwater swale located on the west side of the property, looking south.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 21 :Close up view of stormwater swale located on the west side of the property, looking west.



Photograph 22 :Stormwater swale, Swale #1, located on the east side of the property near the onion hopper from the largest building on the property. View is looking southwest

Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 23 :Close-up view of Swale #1, looking southwest.



Photograph 24 :Water in Swale #1. Strong onion odor noticed in this area.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 25 :Stormwater outfall to Swale #1, looking southwest.



Photograph 26 :Stormwater outfall and water, Swale #1, note onion husk and debris in water.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 27 :Stormwater swale, Swale #2, located on the northeast corner of the property, looking north northeast.



Photograph 28 :Stormwater outfall to Swale #2, looking north.

Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 29 :Swale #2, looking north.



Photograph 30 :Rills on west bank of Swale #2 near south end of the swale.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 31 :Swale #2, mid-way, looking north, note rills along west bank



Photograph 32 :Close-up view of west bank rills, mid-way, Swale #2.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 33 :Swale #2, north end, looking northwest.



Photograph 34 :Close-up view of north end rills, Swale #2.

Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 35 :Swale #2, north end, looking north.



Photograph 36 :Close-up view of erosion area, Swale #2, north end.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 37 :Swale #2, looking southwest. Strong onion odor noticed in this area.



Photograph 38 :Swale #2, looking southwest, note rills on west bank.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 39 :Stormwater swale, Swale #3, located on the north side of the property, looking northwest.



Photograph 40 :Swale #3, northeast end, looking northwest.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 41 :Close-up view of Swale #3, northeast end.



Photograph 42 :Irrigation ditch and vegetation on the north side of the property near Swale #3.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 43 :Close-up view of Swale #3, northeast end, note onion and onion husks.



Photograph 44 :Close-up view of Swale #3, northeast end, note discoloration of soil, appears to be oil or petroleum based.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 45 :Refrigeration oil drums, stored on the north end of the property, near Swale #3. Facility representative indicated the drums contained used oil.



Photograph 46 :Label on one of the drums indicating refrigeration oil.

Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 47 :Refrigeration oil drums, note oil pooling on the top and leaking around the sides.



Photograph 48 :Storage pallets and refrigeration oil drums.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 49 :Leaking oil from refrigeration oil drums on to storage pallets.



Photograph 50 :Refrigeration oil drums, stored near Swale #3, looking east.

Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 51 :Refrigeration oil drums, stored near Swale #3, looking east, second view.



Photograph 52 :Swale #3, west end of the swale, looking east.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 53 :Swale #3, west end of the swale, looking east, second view.



Photograph 54 :Rills on southwest bank of Swale #3.

Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 55 :Swale #3, looking east.



Photograph 56 :Rills on south bank of Swale #3.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 57 :Irrigation ditch on north side of property looking west, note moist soil in ditch bottom does not extend to foreground.



Photograph 58 :Rills on facility property into north side irrigation ditch.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 59 :Irrigation ditch and moist soil on north side of property, looking north.



Photograph 60 :Close-up view of moist soil in irrigation ditch north side of property.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 61 :Large rill on facility property into north side irrigation ditch, looking east.



Photograph 62 :Large rill on facility property into north side irrigation ditch, looking north.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 63 :Irrigation ditch on west side of property looking north.



Photograph 64 :Pooling water in irrigation ditch, west side of the property, looking north.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 65 :Stormwater swale, Swale #4, located on the west side of the property, looking southwest.



Photograph 66 :Swale #4, northeast end, looking southwest, note tire tracks to edge of swale.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 67 :Swale #4, north end, looking northwest.



Photograph 68 :Close-up view of Swale #4 north end.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 69 :Swale #4, looking north from the south end.



Photograph 70 :Close-up view of Swale #4, south end.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 71 :Close-up view of Swale #4, note onions and debris.



Photograph 72 :West side of property near waste water truck loading station, between station and Swale #4, looking northwest.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 73 :West side of property looking at pooling water and Swale #4, facing north.



Photograph 74 :Waste water truck loading station located on the west side of the property.



Idaho Department of Environmental Quality  
Photographic Documentation for Partners Produce, Payette  
Thursday, April 09, 2020



Photograph 75 :View from waste water truck loading station looking west southwest.



Photograph 76 :Rills and waste water from truck loading operations.