



STATEMENT OF CONDITION
ON-SITE WASTE SYSTEM

2499 HIGHWAY 201

NYSSA, OR 97913

The septic system inspected passed satisfactorily according to the State of Oregon & Malheur County Environmental Quality Codes and Regulations.

1. The septic tank was pumped on 1.4.22.
2. The system was inspected on 1.4.22. It can be expected to function satisfactorily and is unlikely to create unsanitary conditions.
3. The system is designed for a commercial property with a residential tie in that flows in through the riser.
4. Septic Tank is rectangular, poured in place concrete, 2,000 Gallons. Tank is in good condition and is part of the original system.
5. Riser is concrete, original, approximately 20x28. Lid is custom fit, thick, plywood.
6. The tank is located approximately 60' west of the grocery store, between two structures.
7. The Inlet baffle is not visible from the maintenance hole.
8. The outlet baffle is not visible from the maintenance hole.
9. Drain Field is working satisfactorily based on the water level observed within the tank prior to pumping. The last maintenance pump was done approximately 18 months ago and was also observed to be functioning appropriately.
10. Water from grocery store was heard flowing into tank.

Signed: _____

Date: 2-8-22

OR License #: 39194

Snake River Septic
4634 S. Rd. H.
Vale, OR 97919
541-709-1508